VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicies

CAMPAIGN No.	5036	DATE	2021/10/15		
MANUFACTURER	KYB Corporation				
	4-1, Hamamatsu-cho 2-chome, Minato-ku, Tokyo, Japan				
DESCRIPTION OF DEFECT	Due to the inappropriate structure of the fixing part of the winding type hopper covinstalled in concrete mixer vehicles, cracks may occur due to vibration during driving vehicle is continued to be used as is, the cracks may progress, and in the worst case sheet and the winding mechanism may fall, obstructing other traffic.				

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-XZU600E	HINO DUTRO	Jul,15,2020~Dec,08,2020	4
2KG-XZU700M		May,12,2020~Dec,15,2020	2
2KG-FC2ABA	HINO RANGER	May,25,2020~Apr,01,2021	20
2KG-FJ2ABA		Apr,29,2020~Apr,05,2021	5
2KG-GC2ABA		Sep,11,2020~Feb,19,2021	2
2PG-FS1AGA	HINO PROFIA	May,11,2020~Mar,22,2021	7
2RG-NKR85N	ISUZU ELF	Jun,25,2020~Mar,29,2021	9
2PG-FSR90S2		Jun,05,2020~Nov,2,2020	4
2PG-FRR90S1	ISUZU FORWARD	Sep,28,2020	1
2PG-FRR90S2		Apr,21,2020~Mar,15,2021	24
2PG-FTR90U2		Jan,20,2021~Apr,08,2021	3
2KG-CXZ60CT	ISUZU GIGA	Jun,16,2020	1
2KG-CXZ77CT		Jul,30,2020~Apr,28,2021	16
2KG-FK72F	FUSO FIGHTER	Jun,03,2020~Feb,18,2021	8
2KG-FK72FY		Feb,09,2021	1
2KG-FK72FZ		Sep,08,2020	1
2DG-FQ62F		Sep,28,2020~Sep,30,2020	2
2KG-FV70HX	FUSO SUPER GREAT	Apr,21,2020~Feb,22,2021	6
2PG-BRR90S1	UD TRUCKS CONDOR	May,06,2021	1
2PG-CW4AL	LID TRUCKS OLION	Jun,01,2020	1
2PG-CW5AL	UD TRUCKS QUON	Sep,16,2020~Oct,13,2020	4
		TOTAL	122

Shipped as replacement parts Shipment period of the subject Parts name Parts number Number of parts parts Winding type hopper cover T2002-00205 Oct,12,2020~May,28,2021 8 Winding type hopper cover T2002-00196 Jun,29,2020~Jul,12,2021 28 2 H0997-04200 Jul,27,2020~Oct,30,2020 Casing Assy TOTAL 38