

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 0 3 5	DATE	Oct. 21. 2021
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Regarding the engine room harness on the vehicle with hybrid system, the gap between bracket for engine control module and the harness may be insufficient due to improper fixing of the harness. While driving, the harness may be worn and then it may short-circuit if the harness was hit on the bracket. In the worst case, this may cause the vehicle not to be able to drive and then not to restart the engine.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-HT32	N I S S A N X-T R A I L	2 0 1 5	13, 667
DAA-HNT32		~ 2 0 2 0	50, 449
		TOTAL	64, 116