

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5041	DATE	Oct. 28. 2021
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain hybrid battery trays of heavy-duty tourist hybrid buses, due to insufficient rust prevention of the tray, the tray has rusted and holes may have formed while in operation. Therefore, water may enter the inside of the tray, which causes the water to adhere to the wiring connection portion of the battery, resulting in a short circuit and a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BJG-RU1ASAR	[HINO Selega]	2008~2010	34
LJG-RU1ASBR		2011~2017	69
QQG-RU1ASBR			
VM-RU2PPFR		2005~2006	8
		TOTAL	111