

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic

CAMPAIGN No.	5047	DATE	November 8, 2021
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	<p>With regards to the snowplows (all-wheel-drive vehicles), due to the inappropriate water proofing process for body earth terminal of RCIOM (Rear Chassis Input/Output Module) connecting harness, water such as rain, melted snow may soak into the RCIOM connector which lead to corrosion. Thus, the warning message may appear in the multi display monitor by conducting failure or short circuit, after which tail lamps and other lamps located vehicle rear might become unlighted.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2DG-CF5AL	Quon	2018 - 2021	210	
2DG-CZ5BL 2DG-CZ5BLKai		2018 - 2021	649	
2DG-HF5AL	-	2018 - 2021	8	
2DG-HZ5BL		2018 - 2021	13	
2DG-SF5AL		2018 - 2021	8	
2DG-SZ5BL		2018 - 2020	11	
			899	