

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5054	DATE	Nov.8 2021
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	In the wheel crane radiators, the fan shrouds of some vehicles have lack of rigidity due to improper design. Therefore, if working continuously, the shroud may deflect while engine running, may contact to the radiator core and coolant may leak from contact portion result to the radiator coolant level alarm lamp may light up.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
YDS-KRC021	KRM-25H	2019~2021	73	
TOTAL			73	