Import Vehicles

CAMPAIGN No.	GAL-3317	DATE	2021/11/10	
MANUFACTURER	Tesla, Inc.			
	(Japanes	Tesla, Inc. ese Importer; Tesla Moto on lateral link on Model 3 using two fasteners. I prect specification, the ate from the sub-frame,	rs Japan)	
DESCRIPTION OF DEFECT	The front suspension lateral link on Model 3 vehicles is attached to the sub-frame using two fasteners. If a fastener is not secured to the correct specification, the fastener may looser over time or separate from the sub-frame, which could cause the lateral link to separate from the sub-frame.			

Commercial name	MODEL YEAR	Number of
	RECALLED	Vehicle
Model 3 RWD	2019	1
Model 3 AWD	2019	5
Model 3 AWD	2019	3
3 kinds	2019	9
	Model 3 RWD Model 3 AWD Model 3 AWD	Commercial nameYEAR RECALLEDModel 3 RWD2019Model 3 AWD2019Model 3 AWD2019