

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5049	DATE	Nov.10.2021
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In a fuel tank made of resin, due to an improper maintenance of welding machine, there is a possibility that welding of joining surface between fuel tank and inlet pipe is insufficient. In this condition, the welded surface could peel off, causing a fuel leak when the tank is full or being refueled.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
DAA-ZWA10	[CT200h]	2020	100	
		TOTAL	100	