

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5053	DATE	Nov. 10. 2021
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain engine control computers of heavy-duty trucks, the failure diagnosis program for the exhaust temperature sensor of the program changed due to the improvement measures of the notification on September 15, 2021 (notification number 5016) is inappropriate. Therefore, these engine control computers may misdiagnose abnormal when the sensor is normal, causing the engine warning light (MIL) to illuminate.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FR1AHA	[HINO Profia]	2019~2021	4,372
2PG-FR1AHG			
2PG-FR1AHJ			
2RG-FR1AHA			
2RG-FR1AHG			
2RG-FR1AHJ			
2SG-FR1AHH			
2SG-FR1AHS			
2PG-FR1AJA		2019~2021	199
2RG-FR1AJG			
2PG-FS1AGA		2019~2021	1,987
2PG-FS1AHA		2019~2021	731
2PG-FS1AHG			
2PG-FS1AHJ			
2RG-FS1AHA			
2RG-FS1AHG			
2RG-FS1AHJ			
2PG-FS1AJA		2019~2021	537
2PG-FW1AHG		2019~2021	11,163
2PG-FW1AHJ			
2RG-FW1AHG			
2RG-FW1AHJ			
2SG-FW1AHH			
2SG-FW1AHS			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FW1AJG	[HINO Profia]	2019~2021	101
2PG-FW1AJJ			
2RG-FW1AJG			
2RG-FW1AJJ			
		TOTAL	19,090