

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5050	DATE	November 11. 2021
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	Tie rod of agricultural tractor is not properly crimped due to improper manufacturing of the tie rod end. Therefore, excessive stress is applied to the tie rod end during steering operation, and if the tie rod end is used as it is, the tie rod end may be damaged, and in the worst case, the tie rod may be broken and steering may become impossible.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
-	「YT463」	2018~2019	79	
	「YT470」	2018~2019	509	
-	「YT488A」	2018~2019	99	
TOTAL			687	