

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5043	DATE	November 12, 2021
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the impeller (resin impeller) of the low-pressure fuel pump for gasoline engine, due to improper molding conditions, the resin density may be low, and it may swell and deform with the fuel. Therefore, the impeller may potentially interfere with the pump case, causing the malfunction of the fuel pump. In the worst case, the engine may stall during driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6BA-DJLAS	Mazda 「Demio」	2018	1,394
6BA-DJLFS		2018	7,056
CBA-DJLFS		2018	71
DBA-DJ3AS		2018	1,135
DBA-DJ3FS		2018	8,215
4BA-DJLFJ	Mazda 「Mazda Kyoshusha」	2019	354
DBA-BM5FS	Mazda 「Axela」	2018-2019	5,376
DBA-BM5FP		2018-2019	2,213
DBA-BM5AS		2018	675
DBA-BM5AP		2018	225
CBA-BM6FJ		2018	462
DAA-BYEFP		2018-2019	391
6BA-GJ5FP	Mazda 「Atenza」	2018	603
6BA-GJ5FW		2018	378

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6BA-GJEFP	Mazda「Atenza」	2018	337
6BA-GJEFW		2018	256
DBA-GJ5FP		2018	4
DBA-GJ5FW		2018	1
DBA-GJEFP		2018	8
DBA-GJEFW		2018	3
6BA-DKEAW	Mazda「CX-3」	2018	878
6BA-DKEFW		2018	3,174
5BA-KF5P	Mazda「CX-5」	2018	45
6BA-KF5P		2018	2,564
6BA-KFEP		2018	3,736
6BA-KG5P	Mazda「CX-8」	2018	20
5BA-ND5RC	Mazda「Roadster」	2018	1,382
5BA-NDERC		2018	1,084
DBA-ND5RC		2018	259
DBA-NDERC		2018	109
ABA-NF2EK	「ABARTH 124 spider」	2018	74
CBA-NF2EK		2018	162
		Total	42,644