

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5055	DATE	Nov. 17. 2021
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain rear underrun protection devices, due to inappropriate instructions for assembling the rear bumper and the spacers, the number of bolts for assembling the rear bumper may be insufficient. Therefore, these vehicles may fail to comply with the requirements of article 18-2 of the safety standard.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FC2ABG	[HINO Ranger]	2021	8
2KG-FD2ABA		2021	2
2KG-FD2ABG			
		TOTAL	10