

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5059	DATE	24. Nov. 2021
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	In the area of the connection between the fuel hose and the pipe, elasticity of the fuel hose is adversely affected by heat treatments in adhesion processes, and the airtightness of the connection area may become insufficient. Therefore, if high fuel pressure is applied to the connection area, fuel may leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-VH02J	XVS400 DragStar	2009~2017	2,865
	XVS400C DragStar Classic	2009~2017	3,187
		TOTAL	6,052