VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	5065	DATE	December 2 ,2021
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		In certain medium-duty buses, the location of a screw for fixing the floor board is not correct so that the tip of this screw may interfere with a fuel pipe. Therefore, the fuel pipe might be damaged, possibly resulting in a fuel leak.	

ТҮРЕ	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
SKG-LR290J2	[ERGA MIO]	2017	10
2KG-LR290J3		2017-2019	51
2KG-LR290J4		2019-2021	40
		TOTAL	101