

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5066	DATE	Dec. 2. 2021
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	In certain medium-duty buses, the location of a screw for fixing the floor board is not correct so that the tip of this screw may interfere with a fuel pipe. Therefore, the fuel pipe might be damaged, possibly resulting in a fuel leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-KR290J2	[HINO Rainbow]	2016~2017	26
2KG-KR290J3		2017~2019	36
2KG-KR290J4		2019~2021	38
		TOTAL	100