

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5069	DATE	December.2. 2021
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	For continuously variable transmission, hydraulic control may have been programmed improperly whereby its metallic belt can be cracked and damaged through frequent repetition of the accelerator operation to open and close the throttle while driving at a constant speed. Should vehicle in such a condition continue in service, the vehicle could have poor starting/acceleration and could be disabled in the very worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
HBD-JJ1	「N-VAN」	2018~2020	60,198
HBD-JJ2		2018~2020	25,192
TOTAL			85,390

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS	PART No.	DELIVERED AS "SERVICE PARTS"	NUMBER OF PARTS
TRANSMISSION ASSY	06210-6F8-N05	2021	3
	06210-6F8-N04	2020	2
	06210-6F9-N04	2020	1
TOTAL			6