

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5068	DATE	Dec. 8. 2021
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain heavy-duty trucks, because the urea water pipe with heating wire and the cooling water pipe are fixed improperly, both pipes may come into contact with each other due to vibration during running, causing the heating wire to be disconnected. Therefore, the engine warning light (MIL) may illuminate, the urea water may freeze at low temperature and NOx in the exhaust gas may increase if it is used continuously.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FH1AGA 2PG-FH1AGG	[HINO Profia]	2017~2020	360
2KG-FN1AGA 2PG-FN1AGA 2PG-FN1AGG		2017~2020	1,706
2KG-FN1AJA 2KG-FN1AJG 2PG-FN1AJA 2PG-FN1AJG		2017~2020	1,790
2PG-FQ1AJG 2PG-FQ1AJJ		2017~2020	1,449
2PG-FR1AGA		2017~2020	179
2PG-FR1AHA 2PG-FR1AHG 2PG-FR1AHJ 2RG-FR1AHA 2RG-FR1AHG 2RG-FR1AHJ 2SG-FR1AHH 2SG-FR1AHS		2017~2020	7,438
2KG-FR1AJA 2PG-FR1AJA 2PG-FR1AJG 2RG-FR1AJG		2017~2020	1,113

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FR1EHG 2KG-FR1EHJ 2PG-FR1EHG 2PG-FR1EHJ	[HINO Profia]	2017~2020	1, 653
2PG-FS1AGA		2017~2020	4, 854
2KG-FS1AHA 2PG-FS1AHA 2PG-FS1AHG 2PG-FS1AHJ 2RG-FS1AHA 2RG-FS1AHG 2RG-FS1AHJ		2017~2020	1, 115
2KG-FS1AJA 2PG-FS1AJA		2017~2020	1, 405
2KG-FS1EGA		2017~2020	1, 415
2DG-FS1EHA 2KG-FS1EHA 2KG-FS1EHG 2PG-FS1EHA 2PG-FS1EHG		2017~2020	1, 008
2DG-FS1EJA 2KG-FS1EJA		2017~2020	792
2PG-FW1AHG 2PG-FW1AHJ 2RG-FW1AHG 2RG-FW1AHJ 2SG-FW1AHH 2SG-FW1AHS		2017~2020	17, 841
2PG-FW1AJG 2PG-FW1AJJ 2RG-FW1AJG 2RG-FW1AJJ		2017~2020	305

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-FW1EHG 2KG-FW1EHG 2KG-FW1EHJ 2PG-FW1EHG 2PG-FW1EHJ	[HINO Profia]	2017~2020	2,868
TOTAL			47,291