

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5070	DATE	Dec.8.2021
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	On the police patrol car, due to improper control program of the siren amplifier, there is a possibility that overcurrent could flow if microphone is used with maximum volume while no siren is operated. If this were to occur, the fuse could blow resulting in siren becoming inoperative.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-ARS220	[CROWN PATROL CAR]	2021	130
6AA-AZSH21			67
		TOTAL	197