

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5071	DATE	Dec .16, 2021
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	The head lamp aiming measurement/adjustment may have been performed with improper position setting of the optical receiver in the head lamp optical axis adjustment facility in the vehicle manufacturing factory. As the result, the head lamp optical axis aiming may not comply with safety regulation in some of the vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE		
3BD-DA17V	EVERY	2021	5			
5BD-DA17V			16			
3BD-DR17V	NV100 CLIPPER		1			
5BD-DR17V			12			
HBD-DR17V			1			
3BD-DG17V	SCRUM		2			
5BD-DG17V			1			
5BD-DS17V	MINICAB		2			
			TOTAL		40	