

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5076	DATE	December. 16. 2021
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Engine cooling system may, due to inadequate control over dies for molding radiator caps, have a radiator cap having smaller allowance for overlap with the filler neck, thereby lacking in sealability. This can eventually cause high-temperature cooling water to spout from the overflow tube, which could cause the rider to get burnt in the very worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-SC83	「Rebel 1100」	2021	1,238
2BL-NC42	「CB400 SUPER FOUR」 「CB400 SUPER BOL D'OR」	2021	1,118
2BL-SC82	「CBR1000RR-R」	2021	198
TOTAL			2,554