

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	5074	DATE	December 20, 2021
MANUFACTURE	TOYOTA INDUSTRIES CORPORATION		
DESCRIPTION OF DEFECT	With the driving devices of internal-combustion engine forklift vehicles, there are cases where strength of axle shaft is insufficient due to improper heating process. There is a possibility that continuous usage under such condition may cause cracks on the axle shaft, and lead to unable to drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBT-8FGJ35	TOYOTA GENE0	2018	3
YDN-A8FDJ35		2018	17
		TOTAL	20