

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5079	DATE	December 24, 2021
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	For forklift trucks, waterproofing of the traveling motor wiring area is inappropriate. Therefore, if the traveling motor gets a large amount of water or salt water on it, water may enter the traveling motor. Consequently, the truck may stop with an error.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAF-M299	「FE25-2」 「FE30-2」	2021	50
		TOTAL	50