

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3330	DATE	24 th December, 2021
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to inappropriate manufacturing management of the exhaust gas recirculation device (EGR), the mechanism for opening and closing the valve flaps can get stuck by deformation of plastic rotor inside the actuator. In case of a clamping EGR flap, the EGR is switched off via the EGR valve and the engine warning light is activated. In this case, it may happen that the exhaust gas limits are exceeded.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3CA-JU8230A	BMW X5 xDrive35d	2021	1
3CA-JU8230S		2021	1
3CA-GT8230S	BMW X6 xDrive35d	2021	1
3CA-TB4230	BMW X7 xDrive40d	2021	1
		TOTAL	4