

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-3335	DATE	Dec. 24. 2021
MANUFACTURER	Ford Motor Company		
DESCRIPTION OF DEFECT	<p>SAFETY RECALL: Explorer Vehicles - Roof Rail Covers Loose - S</p> <p>Certain 2016 Model Year Explorer vehicles built in Chicago Plant (USA) produced</p> <p>On some of the affected vehicles, the roof rail covers may become detached from the vehicle. A detached roof rail cover can create a road hazard for other road users, increasing the risk of crash.</p> <p>Before demonstrating or delivering any new in-stock vehicles involved in this recall, dealers are to inspect and secure both sides of the roof rail covers as described in the technical instructions. This service must be performed on all affected vehicles at no charge to the vehicle owner.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-1FM5KH	Explorer 2.3L FWD	2016	730 units
ABA-1FM5K8	Explorer 3.5L 4WD	2016	101 units
TOTAL			831 units