## VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

## **Domestic Vehicles**

CAMPAIGN No.	5082	DATE	Jan. 6, 2022		
MANUFACTURER	SUZUKI MOTOR CORPORATION				
DESCRIPTION OF DEFECT	The air bag system may fail to deploy properly, due to the improper stitching of the curtain air bag cushion.  As the result, the impact absorbing performance of the curtain air bag may become insufficient in the event of the vehicle collision.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
3BA-HA37S	A I TOO	2021	1,073	
5AA-HA97S	ALTO		249	
		TOTAL	1,322	