

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3340	DATE	January 19, 2022
MANUFACTURER	Audi (Japanese Importer: VOLKSWAGEN Group Japan KK)		
DESCRIPTION OF DEFECT	Due to an error in the manufacturing process for the air spring strut, a groove in the area of the retaining clip may not have been manufactured according to the specifications. This means that the clip may not be securely seated in the groove. In the worst case, the clip slips out of the groove, air will escape from the affected air spring strut and the vehicle will drop on one side with the warning message.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-FWEBGE	Audi RS e-tron GT	2022	1
		Total	1