

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5084	DATE	January 20, 2022
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	<p>In a hybrid vehicle, while driving, due to improper program of the engine control computer used for the power generation, the engine may not restart during acceleration immediately after stopping the engine. As a result, the engine warning lamp turns on and lack of acceleration occurs. If a vehicle with this condition is continuously used, in the worst case, the vehicle may not be able to run due to low battery power.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5AA-A202S	ROCKY	2021	3,421
5AA-A202A	RAIZE		7,928
		TOTAL	11,349