## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	外-3342	DATE	21 <sup>st</sup> , Jan, 2022
MANUFACTURE	Tesla, Inc. (Japanese Importer; Tesla Motors Japan)		
DESCRIPTION OF DEFECT	The secondary frunk (Front trunk) latch actuates into position at the back of the frunk striker. On some Model S vehicles, the latch assembly may be aligned too far rearward. While this alignment does not impact latching of the primary latch with the frunk striker, it may prevent latching of the secondary latch. If the primary latch is inadvertently released and the secondary latch is not engaged, the frunk may open without warning and obstruct the driver's visibility, increasing the risk of a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-SWL1S		2015	176
ZAA-SL2SA		2015, 2016	98
ZAA-SWL2SA	Model S	2015, 2016	27
ZAA-SWL2S2A		2015	84
None		2017 - 2020	967
		TOTAL	1352