

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5085	DATE	Jan.26.2022
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the rear turn signal lamp(s), due to improper water resistance of the circuit board in the LED socket, there is a possibility that condensation could form on the circuit board by the water, such as rain, dropping on the socket. In this condition, short circuit could occur on the circuit board by repeated cycle of current application with condensation and drying of condensation, and in the worst case, the rear turn signal lamp(s) could become inoperative.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6BA-MXUA80	[HARRIER]	2020-2021	37,049
6BA-MXUA85			5,040
6AA-AXUH80			18,704
6AA-AXUH85			9,253
		TOTAL	70,046