

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5 0 8 8	DATE	1. Feb. 2022
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Regarding the accelerator, due to insufficient strength of the throttle grip, if the grip is rotated slightly and pulled outward to raise the vehicle upright, and so on, excessive force may be applied and cracks may form. Consequently, the grip may become caught when the grip is operated, and in the worst case, it may not be possible to increase or decrease the engine speed.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-RN70J	TRACER900 GT	2021	563
		TOTAL	563