

**VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN**

Domestic Vehicles

<b>CAMPAIGN No.</b>	<b>5086</b>	<b>DATE</b>	<b>Feb. 3 , 2022</b>
<b>MANUFACTURER</b>	<b>SUZUKI MOTOR CORPORATION</b>		
<b>DESCRIPTION OF DEFECT</b>	<p>The owner's manual does not comply with the vehicle safety regulation section 22, as the necessary note is not indicated for the ISO/R3 Child restraint system (CRS) installation, in the table of information on ISOFIX CRS system installation suitability.</p> <p>However, the above situation does not affect the function of the CRS when it is fixed on the vehicle.</p>		

<b>TYPE</b>	<b>COMMERCIAL NAME</b>	<b>MODEL YEAR RECALLED</b>	<b>NUMBER OF VEHICLES</b>
<b>DBA-YD21S</b>	<b>ESCUDO</b>	<b>2015~2017</b>	<b>814</b>
<b>DBA-YE21S</b>		<b>2015~2018</b>	<b>6,119</b>
<b>CBA-YEA1S</b>		<b>2017~2018</b>	<b>2,748</b>
<b>4BA- YEA1S</b>		<b>2018~2021</b>	<b>6,173</b>
		<b>TOTAL</b>	<b>15,854</b>