

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	5094	DATE	February 3 ,2022
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		On certain heavy duty trucks, durability of the brake hose for air brake is insufficient due to inappropriate operation in its manufacturing process. Consequently, if the vehicle continues to be used under the condition, the brake hose may break and air may leak, causing the brake warning lamp to turn on and the braking force to decrease.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-CYE60CM	[GIGA]	2021	5
2KG-CYG60CM		2021	9
2PG-CYH77C		2021	5
2KG-CYJ77C 2KG-CYJ77CA 2PG-CYJ77C 2PG-CYJ77CA		2021	192
		TOTAL	211