

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5097	DATE	February 10,2022
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Due to an inappropriate specification, the driver airbag may not inflate into an optimal shape when deployed. Therefore, in the worst case scenario, the airbag's performance may not be fully demonstrated under certain conditions.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5AA-B34A	「eK SPACE」	2020~2021	7,607
4AA-B35A		2020~2021	2,628
5AA-B37A		2020~2021	1,482
4AA-B38A		2020~2021	1,459
5AA-B44A	「ROOX」	2020~2021	45,093
4AA-B45A		2020~2021	17,455
5AA-B47A		2020~2021	7,041
4AA-B48A		2020~2021	3,517
		TOTAL	86,282