

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3353	DATE	February. 10. 2022
MANUFACTURER	Honda Vietnam Co., Ltd.		
DESCRIPTION OF DEFECT	Engine electronic control unit may lack noise immunity because an improper selection of capacitors was made. In this case, the engine warning light can fail to come on in the event of disconnection of the O2 sensor.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BJ-JK03	「Dio110」	2020~2021	4,415
TOTAL			4,415