

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5100	DATE	February 14, 2022
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	The springs of the accelerator pedal that install on forklifts may not have enough strength. The continuous use can break the springs. In the worst case, the accelerator pedal can't return to the normal position and may keep full accelerator. In that case, the forklift can be stopped by using brake and may not be able to travel even if return on key switch after turning off key switch.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
M190		2002-2005	228
M190T		2005-2006	30
ZAF-M190T		2006	89
M193		2003-2005	29
M193T		2006	7
ZAF-M193T	FB20 FB25	2006-2011	82
ZAF-M193TK	FB20 FB25	2011-2014	78
M194		2005	2
ZAF-M194T		2006-2010	4
M195		2004	1
ZAF-SM236	FB09H FB10 FB14 FB15 FB15HB	2006-2011	489
ZAF-SM236K	FB09H FB10 FB14 FB15 FB15HB FE15	2011-2020	1484

ZAF-M237	FB18 FB20A	2007	1
ZAF-SM237	FB18 FB18HB FB20A FB20AHB	2006-2011	135
ZAF-SM237K	FB18 FB18HB FB20A FB20AHB FE18	2011-2020	424
ZAF-M238	FB09ML FB10ML FB13ML	2006-2011	36
ZAF-M238K	FB09ML FB10ML FB13ML	2011-2020	94
ZAF-M239	FB15ML	2007-2011	50
ZAF-M239K	FB15ML	2011-2020	122
ZAF-SM243	FB15G FB18G FB20AG	2007-2010	4
ZAF-M254	FB20HB FB25HB	2008-2011	3
ZAF-M254K	FB20HB FB25HB	2011-2013	3
TOTAL			3,395