

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3355	DATE	February 28 th , 2022
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to inappropriate manufacturing of characteristic map thermostat, possible burr residue may cause the coolant entering the plug connection. In this case, the engine control unit may detect malfunction, and this then results in a CC message (MIL on).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-7R44	「BMW 750i xDrive」	2021	1
3BA-JU44A	「BMW X5 M50i」	2021	1
3BA-JU44S			1
3BA-CY44	「BMW X6 M50i」	2021	3
3BA-CX44	「BMW X7 M50i」	2021	8
3BA-JS44	「BMW M550i xDrive」	2021	4
3BA-BC44	「BMW M850i xDrive Coupe」	2021	1
3BA-GV44	「BMW M850i GranCoupe」	2021	4
		TOTAL	23