

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4886	DATE	Feb.3.2021
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the exhaust gas emission prevention system of the subject vehicles, due to improper programming of the engine ECU, information on turbocharger fault diagnosis is not transmitted to the engine ECU. In this condition, the engine warning light will not illuminate when the turbocharger failure occurs.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-XZB60 2PG-XZB60	[TOYOTA COASTER]	2019-2020	382
2KG-XZB70 2PG-XZB70			1,542
2KG-XZB80			8
2PG-XZB60V 2PG-XZB70V	[TOYOTA COASTER BIG VAN]	2019-2020	60
			27
2KG-XZB60M 2PG-XZB60M	[HINO LIESSE II]	2019-2020	221
2KG-XZB70M 2PG-XZB70M			1,108
2KG-XZB80M			9
2PG-XZB60Y 2PG-XZB70Y	[HINO LIESSE II BIG VAN]	2019-2020	4
			47
		TOTAL	3,408