

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4888	DATE	February 4, 2021
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>Antilock brake system (ABS) modulator may have had excessive grease applied to its reservoir piston O-ring by inadequately controlled grease application equipment. Through frequent repetition of braking, excess grease can migrate to the OUT valve, where foreign matters can get deposited. Should such foreign matters get caught in the check valve, the braking and stopping distance could become longer than expected.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-SD10	「CRF1100L Africa Twin」	2019	132
		TOTAL	132