

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4891	DATE	2.10.2020
MANUFACTURER	AUTECH JAPAN INCORPORATED		
DESCRIPTION OF DEFECT	Assembling a dump truck of NT100 CLIPPER, a worker forgot to fastened the shift cable with a bolt. So the blow-by hose is rubbed with the shift cable by running vibration. There is a possibility that the blow-by hose finally get holes, and the blow-by gas is discharged into the air.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
EBD-DR16T	NT100 CLIPPER	2020	14
		TOTAL	14