

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	4 8 9 4	DATE	February 15, 2021
MANUFACTURER	ISEKI & CO., LTD.		
DESCRIPTION OF DEFECT	Bearing in the motor for the engine cooling fan of combine harvester is broken because there are wrong parts in this motor caused by inappropriate production process management. This broken bearing cannot activate the cooling fan, which may result in overheat of engine at worst.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-H164	「HFR463」	2020	4
YDN-H165	「HFR450」	2020	5
		TOTAL	9