

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4899	DATE	Feb 19, 2021
MANUFACTURER	SAKAI HEAVY INDUSTRIES, LTD.		
DESCRIPTION OF DEFECT	<p>In the drive device of the road roller, since the painting instruction of the oscillating machine case is inappropriate, the coating of the bolt mounting surface for mounting the traveling motor and the oscillating machine case is peeled off, and the tightening force of the mounting bolt is reduced. Therefore, if the bolt is used as it is, the bolt may loosen and the gear oil may leak from the traveling motor mounting surface.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDP-1MW3	「MW700-1」	2012 - 2014	47
TOTAL			47