

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4903	DATE	Feb. 22. 2021
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain emission control devices, due to the inappropriate program of the engine control computer, the turbocharger does not transmit the failure diagnosis result to the engine control computer. Therefore, even if the turbocharger fails, the engine warning light is not illuminated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-XZC645M	[HINO Dutro]	2019	1
2RG-XZU600E		2019~2020	2
2RG-XZU600T			
2RG-XZU605M		2020	1
2RG-XZU640M		2019	1
2RG-XZU712M		2019	1
		TOTAL	6