VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 8 9 8	DATE	Feb. 25. 2021	
MANUFACTURER	NISSAN			
DESCRIPTION OF DEFECT	Regarding the radiator mount bracket for fixing to the vehicle body, because the operator did not fix the bolts, the radiator may move, causing the radiator hose to come off and the cooling water to leak. Therefore, if the driver continues to drive in this condition, overheating may occur.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-HT32	NISSAN X-TRAIL	2020	9
DAA-HNT32			14
		TOTAL	23