

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4931	DATE	April 1, 2021
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	High-beam headlights may allow water to enter the relay terminal area while driving in rain or other bad weather conditions, because the cover attached to the headlight relay has faults in its waterproof structure. If such water ingress occurs, the headlight driver may falsely detect it as the switching to high beams whereby the headlight high beam indicator light can fail to go on when the high beams are actually switched on.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-PC40	「CBR600RR」	2020-2021	734
		TOTAL	734