

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4922	DATE	Apr. 1. 2021
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain fuel hoses of heavy-duty buses, due to inappropriate instructions for assembling the insertion amount of the molded hose, stress may be concentrated on the bent portion and cracks may occur when the insertion amount is large. Therefore, if the bus is continued to be used, cracks may develop and fuel may leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARK	
QDG-KV290N1 QKG-KV290N1	[HINO BlueRibbon]	2015~2017	355		
2DG-KV290N2 2KG-KV290N2 2TG-KV290N2		2017~2019	242		
2DG-KV290N3 2KG-KV290N3 2TG-KV290N3		2019~2020	129		
QKG-KV290Q1 QPG-KV290Q1 QRG-KV290Q1		2015~2017	294		
2DG-KV290Q2 2KG-KV290Q2 2PG-KV290Q2 2TG-KV290Q2		2017~2019	282		
2PG-KV290Q3 2RG-KV290Q3 2TG-KV290Q3		2019~2020	149		
		TOTAL	1,451		

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS	REMARK
fuel hoses	SX001-16503	2019~2021	42	
	SX001-16504	2018~2021	55	
		TOTAL	97	