

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4921	DATE	April 1 ,2021
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		In some heavy-duty buses, the assembly variation of the fuel hose due to improper assembly instructions may cause stress to concentrate on the bending portion of the hose, which could lead to cracks. Consequently, if the component in question continues to be used without repair, the cracks could develop into a hole and make the fuel leak.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QDG-LV290N1 QKG-LV290N1 QPG-LV290N1	[ERGA]	2015-2017	1,048
2DG-LV290N2 2KG-LV290N2 2PG-LV290N2 2TG-LV290N2		2017-2019	1,174
2DG-LV290N3 2KG-LV290N3 2PG-LV290N3 2RG-LV290N3 2TG-LV290N3		2019-2020	810
QDG-LV290Q1 QKG-LV290Q1 QPG-LV290Q1 QRG-LV290Q1		2015-2017	273
2DG-LV290Q2 2KG-LV290Q2 2PG-LV290Q2 2TG-LV290Q2		2017-2019	318
2KG-LV290Q3 2PG-LV290Q3 2RG-LV290Q3 2TG-LV290Q3		2019-2020	194
		TOTAL	3,817

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF VEHICLE
Fuel Hose	8-98317382-0 8-98317383-0	2017-2021	607
		TOTAL	607