

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3198	DATE	April 7, 2021
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	The sealing pin may be missing in the engine control unit connectors due to a deviation in supplier's wiring harness manufacturing process. As a result, moisture may enter the affected connector and connector gets rusted, and in the worst case, the engine warning lamp coming on and/or the engine operating in emergency running mode with reduced power.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-F8CWWF	Audi S8	2020	1
AAA-F8CXYF	Audi A8 60Tq	2019-2020	4
AAA-F8CXYL	Audi A8L 60Tq	2019	1
		Total	6