

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4933	DATE	Apr.7.2021
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the rear seat belt reminder system of the subject vehicles, due to improper programming in the combination meter, there is a possibility that the seat belt buckling / unbuckling status could be detected incorrectly when the hybrid system starts. In this condition, the rear seat belt reminder indicator will not illuminate correctly, resulting in noncompliance with the requirement prescribed in “Safety Regulations for Road Vehicles”, Article 22-3 (requirement of seat belt).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6AA-AXVH70	[CAMRY]	2021	1,084
6AA-AXVH75			122
6AA-AXVH70N	[ALTIS]		4
6AA-AXVH75N			2
		TOTAL	1,212