

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4935	DATE	April 8, 2021
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Shock absorber may, concerning the cushion connecting plate connecting the rear cushion arm and the swing arm, incorporate a plate which was assembled inside out due to inadequate assembling work instructions. Through frequent repetition of bumpy ride, such a plate can be damaged or broken and, in the very worst case, the vehicle's running stability could be thereby impaired.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-SC82	「CBR1000RR-R」	2020	439
		TOTAL	439