

## VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4929	DATE	Apr. 8, 2021
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	The breather pipe may not be properly welded to the fuel tank, due to the improper manufacturing process of the resin made fuel tank. Therefore, the welded portion may be detached by the factors such as the vehicle vibration in normal usage of the vehicle, and it could cause fuel leakage from the affected area when the fuel tank is filled to the top.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
DBA-MA26S	SOLIO	2020	1,109	2 WD vehicles only
DAA-MA36S			4,049	
DAA-MA46S			252	
DAA-MN71S	XBEE		987	
4AA-MN71S			794	
5AA-FF21S	IGNIS		305	
DAA-MB36S	DELICA D:2		290	
DAA-MB46S			16	
		<b>TOTAL</b>	<b>7,802</b>	