

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4938	DATE	Apr.15,2021
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	<p>In the engine control computer of a turbo vehicle, the intake pipe's pressure sensor was not set to properly judge abnormalities. As a result, the sensor may incorrectly detect abnormalities when decelerating in environments of low atmospheric pressure such as high altitude. Therefore, if a vehicle with this condition is continuously used, the engine warning lamp may turn on and the electronic stability control may not be applied while driving.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5BA-LA650S	TANTO	2020-2021	7,758
5BA-LA660S			1,710
5BA-LA650F	CHIFFON	2020-2021	186
5BA-LA660F			74
TOTAL			9,728